



Frank Cheng
<FCheng@dtsc.ca.gov>

06/14/2005 02:53 PM

To Richard Muza/R9/USEPA/US@EPA,
content.arnold@navy.mil, frank.piszkin@navy.mil,
jbroderic@rb8.swrcb.ca.gov

cc

bcc

Subject comments on Group 2 PRLs

We have the following comments:

PRL 51

1) Waste retrieved from the service sink in Bldg 51 was hazardous. The report recommends removing the material from the drain, and GSU concurs with that recommendation.

2) The Navy should propose to investigate the sewer lines leading from this sink. The Navy should propose sampling in downstream locations likely to allow the accumulation of waste, and propose soil matrix sampling below any breaks, leaks, or discharge points where the sewer contents may have been released to the environment.

3) Three soil borings installed outside Bldg 51 were near a storm drain inlet, a grease trap, and between Bldg 51 and the probable course of the storm drain line, near the sanitary sewer. The soil matrix samples retrieved in these borings were analyzed for total petroleum hydrocarbons, VOCs and SVOCs. GSU does not regard this suite of analysis as suitable to rule out contamination with hazardous metals. The Navy should propose additional sampling and analysis to rule out metals contamination at this PRL.

Frank Cheng, P.E.
Office of Military Facilities
Department of Toxic Substances
5796 Corporate Avenue
Cypress, California 90630
Phone: (714) 484-5395
Fax: (714) 484-5437